

SB AD32/05

Revision: 1.1

TITLE:	Software Update to Version 2.72		
DOCUMENT NUMBER:	SB AD32/05		
EQUIPMENT:	AD32 Air Data Display		
© Copyright by THOMMEN AIRCRAFT EQUIPMENT AG, CH-4132 Muttenz, Switzerland			

Legal Notice:

This document and the information enclosed are proprietary data of THOMMEN AIRCRAFT EQUIPMENT AG. Neither this document nor the information contained shall be used, reproduced, or disclosed to others without the written authorization of THOMMEN AIRCRAFT EQUIPMENT AG, except to the extent required for installation or maintenance of the recipient's equipment(s).



SB AD32/05

Revision: 1.1

RECORD OF REVISIONS

Rev.	Date	Reason for Revision	Prepared	Checked	Approved
1.0	07/05/12	Initial Release	R. Wehrli	-	K. Gisler
1.1	26/04/21	Service Bulletin reformatted. No changes to the technical content.	J. Garrett	O. Diatlova	A. Savin



SB AD32/05

Revision: 1.1

SERVICE BULLETIN

1. Planning Information

A. Effectivity

The minor modification MOD00B described in this Service Bulletin applies to the AD32 Air Data Display with part numbers and configuration ID numbers as listed below:

PART NUMBER	CONFIGURATION ID	
AD32.32.53F.28.1.DA	8110	
AD32.32.35F.28.1.DF	8034	

B. Concurrent Requirements

None required.

C. Reason

This document is issued to provide information about the software change to version 2.72 for the AD32 Air Data Display.

D. Description

The software modification prevents the occurrence of failure code FC005 on the part numbers stated above.

E. Compliance Recommendation

Accomplishment of this Service Bulletin is optional.

F. Approval

The AD32 Air Data Display conforms to TSO-C106, TSO-C88a, and TSO-C10b.

This Service Bulletin contains no modification information that revises the approved configuration and therefore does not require any implementation of governmental or other regulatory agency approval.

G. Manpower

This modification can be done by THOMMEN AIRCRAFT EQUIPMENT AG or its approved service centres.

H. Weight and Balance

Not affected.

I. Electrical Load Data

Not changed.

J. Software Accomplishment Summary

Refer to paragraph 1C, Reason (for the software accomplishment).



SB AD32/05

Revision: 1.1

K. References

None.

L. Other Publications Affected None.

M. Interchangeability of PartsNot applicable.



SB AD32/05

Revision: 1.1

2. Material Information

A. Material - Price and Availability

The software version 2.72 required for this modification is provided by THOMMEN AIRCRAFT EQUIPMENT AG, or its approved service centres.

Installation of this Service Bulletin is subject to no special pricing.

For more information, please contact:

THOMMEN AIRCRAFT EQUIPMENT AG Technical Support Department Hofackerstrasse 48 CH-4132 Muttenz Switzerland

Tel: +41 (0)61 965 22 22 Fax: +41 (0)61 965 22 88

NOTE:

All units subject for modification must be scheduled prior to shipping. Contact THOMMEN AIRCRAFT EQUIPMENT AG for further lead time and delivery schedule.

B. Tooling - Price and Availability

No special tools are required.



SB AD32/05

Revision: 1.1

3. Accomplishment Instructions

A. Procedure

The modification procedure can be accomplished by THOMMEN AIRCRAFT EQUIPMENT AG or its approved service centres.

B. Testing

Testing can be accomplished by THOMMEN AIRCRAFT EQUIPMENT AG or its approved service centres.

C. Modification Status Marking

Identification plates are attached externally to the instrument housing.

The MOD columns will identify the modification status.

The TSO nameplate identifies the AD32 Air Data Display by part number and configuration ID number:



The status label shows the LRU's HW/SW version and MOD status:

