

GENERAL

The List of Service Bulletins shows the Service Bulletins available to customers and/or service centers for equipment manufactured by Thommen Aircraft Equipment AG.

The List of Service Bulletins has the following equipment categories:

- Air Data Computer / Air Data Display

CONTACT ADDRESS:

THOMMEN AIRCRAFT EQUIPMENT AG

Hofackerstrasse 48

4132 MuttENZ

Switzerland

Telephone: +41 (0)61 965 22 22

Email: info@thommen.aero

LIST OF SERVICE BULLETINS (SB)

LST 393

Revision: 2.08

REVISION	DATE	REASON FOR REVISION	NAME
2.03	09 Dec, 2020	General update, revision table added and formatting changes. SB AD32/06 added.	J.Garrett
2.04	10 May, 2021	SBs for pressure switches moved from Air Data Computer / Air Data Display section to Pressure Switch / Indicator section. Five SB updates for AD32/AC32 (dated April 26 th , 2021). Corrections to descriptions and effectivity.	J.Garrett
2.05	24 May, 2022	All documents for equipment manufactured by Sathom Sarl removed (now in LST 396).	J. Garrett
2.06	04 Sep, 2023	SB AC32/07 added	A.Siva
2.07	16 Jul, 2025	SB AD32/08 added	A.Siva
2.08	06 Oct, 2026	SB AD32/08 updated to new Revision 1.1	A. Siva

LIST OF SERVICE BULLETINS (SB)

LST 393

Revision: 2.08

SB No.	REV	DATE	DEVICE EFFECTIVITY	DESCRIPTION
AIR DATA COMPUTER / AIR DATA DISPLAY				
SB AD32/AC32/01 Air Data Computer Air Data Display	1.1	Apr. 26, 2021	AD32 RVSM and AC32	Hardware and Software Update
SB AD32/02 Air Data Display	1.2	Apr. 26, 2021	AD32.32.53F.28.1.RA.(9031) AD32.32.53F.05.1.RB.(9051) AD32.32.53F.05.1.RB.(9053) AD32.42.53F.05.1.RB.(9053) AD32.42.53F.05.1.RC.(9041) AD32.32.53F.28.1.RE.(9010)	Configuration Update to MOD02C
SB AD32/03 Air Data Display	1.1	Nov. 12, 2018	AD32 RVSM	Software Change on the AD32 RVSM Air Data Display: Calculation of barometric corrected Altitude.
SB AD32/AC32-03 Air Data Computer Air Data Display	1.1	Apr. 26, 2021	AD32 RVSM and AC32 made up to and including Mar 2012	Security of PCB Attachment Screws
SB AC32/04 Air Data Computer	1.1	Apr. 26, 2021	AC32.10.21.11.AN	Hardware Version 2.20 to 2.21 – Resistor Change on ARINC Module
SB AD32/05 Air Data Display	1.1	Apr. 26, 2021	AD32.32.53F.28.1.DA (8110) AD32.32.35F.28.1.DF (8034)	Software Update to Version 2.72
SB AD32/06	1.0	Sep 04, 2019	AD32 with HW 4.10	Hardware Modification for AD32 Air Data Display (HIRF compliance according to JAA INT/POL/27&29/1)
SB AC32/07	1.0	Sep 04, 2023	AC32 RVSM / Non RVSM	Power Module Replacement
SB AD32/08	1.1	Oct 06, 2026	AD32 with HW 4.10	Antivibration measure for AD32 HW4.10